	Lead Tes	ting Resul	ts from Sເ	Immer 2022
Jewett Elementary	Test Location	Result ppb		Remediation
	RM 1	4.9	fail	remove from service and re-plumb / retest Oak Grove Spring Water Bubbler
	RM 2	9.2	fail	remove from service and re-plumb / retest Oak Grove Spring Water Bubbler
	RM 3	3.1	pass	
	RM 4	3.2	pass	
	RM 5	257	fail	remove from service and re-plumb / retest Oak Grove Spring Water Bubbler
	RM 6	47.6	fail	remove from service and re-plumb / retest Oak Grove Spring Water Bubbler
	RM 9	11.9	fail	remove from service and re-plumb / retest Oak Grove Spring Water Bubbler
	RM 10	21.8	fail	remove from service and re-plumb / retest Oak Grove Spring Water Bubbler
	RM 19	8.4	fail	remove from service and re-plumb / retest Oak Grove Spring Water Bubbler
	RM 20	2.1	pass	
	RM 21	<1	pass	
	RM 22	<1	pass	
	RM 26	3	pass	
	RM 29	6.2	fail	remove from service and re-plumb / retest Oak Grove Spring Water Bubbler
	Kitchen	2.4	pass	
	Hall Fountain #1	<1	pass	
	Hall Fountain #2	1.7	pass	
	Hall Fountain #3	<1	pass	
Bucksport High School				
	Test Location	Result ppb		
	Gym Fountain Girl's	<1	pass	
	Gym Fountain Boy's	<1	pass	
	Science Wing Fountain	1.8	pass	
	Lobby Fountain	<1	pass	
	Second Floor Fountain	<1	pass	
	Kitchen North Sink	167	fail	add filter and re-plumb / retest
	Kitchen South Sink	11	fail	add filter and re-plumb / retest